

| External List | |
|--|--|
| Product | Item Update Description |
| Accessories Updated - For certain pump m | odels, when adding the Suction Guide, the resulting price is not accurate [Brazil Market] |
| Resovled - FTV option not liste | d in Submittal output (Incident #162815) |
| Armstrong Integrated Designer Resolved - When printing outp | ut, load profile error displayed [UK Market] |
| Updated - Parallel piping confi | iguration added to submittal output when selecting Armstrong Integrated designer (Incident #166633) |
| Boosters Updated - During selection of | Booster, various models not inlcuded in Grid Results |
| Circulators Added - "Fixate on motor" opti | ion for selection of models 1050 & 1060 |
| Control Systems Resolved - When "DP Across C | Chillers/Boilers + Zone Sensors" option is selected for IPS4500, SE-F10 and SE-F20 Variable Primary NCP is getting added [India Market Inclusion] (Incident #176726) |
| Resolved -When selecting Chi | ller Plant Control, the Product Available dropdown was blank. After clicking Get Result, the Post-Select page incorrectly displayed SE-A10 [Asia Pacific Rim Market] |
| Resolved - Submittal pages no | pt printed correctly (Incident #165304) |
| Fire Systems Resovled - Error displayed who | en selecting Get Results during Replacement Jockey Pump Controller selection [Latin America Market] |
| Removed - Removal of Fire Pu | ımp models 3x3x8FM & 8x8x13 selection due to introduction of new VIL models – 8x6x18PF and 4x3x9NF (Incident #175507) |
| Updated - Various Fire System | product lead times [CA and USA Markets] (Incident #175354) |
| Resolved - Brazed Plate Heat F | Exchanger ARMS request displays error [NEMA Market] |
| Heat Exchangers Added - 100% Stainless Steel | option available for sizes 4" - 12" (Incident #173119) |
| Added - SE ETS added to ADEF | PT Select [Latin America Markets] |
| Launch - Brazed Plate Configu | rator |
| | requests, pricing was not accurate (Incident #173673) |
| LPC Resolved - Electric Wet Riser r | not selectable (Incident #176663) |
| Resolved - Stainless steel option is not available in selection and only selectable post selection [Latin America Market] | |
| Resolved - In certain pump sel | lections, the horsepower curve is inaccurate (Incident#177444) |
| Resolved - Specific pump curv | res inaccurate data displayed (Incident #171549) |
| Resolved - Specific pumps not | t displaying 3hp option (Incident #174830) |
| Updated - Available motor opt | ions available for Express Pump option [UK Market] (Incident#172717) |
| Resolved - Service Kit option is | s not available for model 4300 8049-015.0 (Incident #173900) |
| Pumps Updated - Request to add .625 | 5 and .75 size of SSC-SSC L EPSS 2A seal under pump accessories service parts (Incident #172703) |
| Resolved - Inaccurate frame s | ize listed in submittal for 2.5x2.5x7.5 15hp 3600rpm pump models (Incident #172702) |
| Resovled - Certain pump mod | els were missing option to select 5hp and 10hp (Incident#170619) |
| Added - G30P seal [India Mark | et] |
| Added - option for single pump | o selection within Armstrong Integrated Designer (AID) |
| Resolved - Specific 4300 pumi | p models with 1hp, not available within Grid Results (Incident #129365) |
| Update - Various motor select | ions lead time (Incident #175792) |
| Selection Updated - DEVA updated for re | ecently release pump models |
| Resovled - Under certain selections, when Recommended Spare Parts report is selected for print out, an error is displayed (Incident #123969) | |
| Updated - Pricing inacurracy for | or Smart Starup and Smart Startup+ for 0.25-0.33hp (Incident #173245) |
| Service Resolved - In specific cases, d | uring selection, can not select Services from within services and Parts option (Incident #165544) |
| Resolved - Under certain scen | arios, When Expedite (Consult Factory) process is completed, can not place order (Incident #175378) |
| Resolved - During selection of | |