

Product	Item Update Summary
Boosters	Resolved - Boosters with VIL Pumps configurator inaccurate preselect page options (IEC Market)
	Resolved - Booster Submittal specification for Water Supply inaccurate (Incident #138030)
Expansion	Resolved - AX-V model Submittal inaccurate bladder integrity system details (Incident #138159)
Fire Systems	Updated - 6x5x12MF and 8x6x15MF table data
	Added - Fire Systems Order Acknowledgement print out includes Shaft and Sleeve item (Incident #137245)
	Updated - Various DE Fire Pump Features & Options (Incident #137432)
	Updated - Diesel options alignment
	Resolved - Specific order results in order not process error
	Updated - DE Fire 4x3x10PF curve (Incident #107408)
iFMS	Updated - Unrequired popup displayed for iFMS products. (NEMA Market)
Order Processing	Updated - Specific currency adjustments GBP to EUR (Incident #136916)
Pumps	Resolved - When selecting SoS, Submittal, Specification with Include All EquipmentError on printing submittal for print output, error displayed
	Added - Armstrong Integrated Designer pump selection Submittal specifications detail report
	Resolved - Design Envelop Sensorless 4380 inlet/outlet listed specification incorrect (Incident #133889)
	Updated - Special Instructions notice for preliminary data
	Updated - Electricity cost globally each region
	Added - Brook Crompton Motors for DE 4200H pumps (Incident #136490)
	Updated - Changes / Additions to TM65 report data
	Resolved - Multi-Pump configurator missing 4 curve option selection (EMA & IEC Market)
	Resolved - Various price mismatch for Compass R60-50 DI, Compass R60-50 SS
	Updated - DEPM weights (Incident #137751)
	Added - Request to incorporate CFP for All 6-Pole selections (IEC Market) (Incident #137988)
	Resolved - 4200H DEPM IVS incorrect inlet and outlet size (IEC Market) (Incident #137471)
	Resolved - NCN RE: 6" 4200H ES UAT BOM Issues (Incident #138277)
	Resolved - Issue with VFD IP54 Rating (Incident #138242)
	Resolved - Sensorless Bundle is not consistently added to the selection automatically. (Incident #138152)
	Resolved - Incorrect impeller diameter listed for 4200H 1015-011.0 DEPM IVS (Incident #138220)
	Resolved - NPSHR curve is displayed wrong
	Resolved - Inaccurate DE pump recommendation for 360 m3/hr @ 36 m head (Incident #138500)
	Resolved - Not able to select multiple Tango 4332 pumps (Incident #138525)
	Updated - Limited power supply option due to market limitations (NEMA market) (Incident #138525)
Updated - Pacdor drawings for 3x3x5 and 2x2x5 (Incident #100078)	



FILE NO.: 9.010
DATE: February 20, 2025
SUPERSEDES: 9.010
DATE: January 16, 2025

Product	Item Update Summary
Service	Validated - Pump Manager price inconsistency (Incident #113201)
	Updated - Replacement motor selected with incorrect inaccurate price (Incident #115765)
Shell & tube	Resolved - Selecting MBH for the units, system uses BTU and not the MBH (Incident #87437)
User Experience	Updated - Quote menu tab order changed
	Resolved - NCP Status not updating in alignment with process outcome