

| Product         | Item Update Description                                                                                                                                                  |
|-----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Air Separators  | Updated - VA-4 UM lead time (Incident #153310)                                                                                                                           |
| Boosters        | Updated - Sepecific Booster series models lead time (Incident #165989)                                                                                                   |
| DEVA            | Resolved - Error displayed when selecting "Post to DEVA" after selection completed                                                                                       |
| Expansion Tanks | Resolved - In some instances, inaccurate item weight is displayed (Incident #167956)                                                                                     |
| Fire Systems    | Resolved - Innaccurate curve duty points plotting for 5x4x9PF-125hp DE VIL Fire pump                                                                                     |
|                 | Resolved - When 5x4x9 PF CS Fire Pump is selected via Replacement listed fire pump and Driver, error displayed                                                           |
|                 | Added - FM-approved range added for DE VIL Fire Pump 5x4x10PF (Incident#168894)                                                                                          |
|                 | Disabled - Selection of 12x8x20F impeller selection from grid results (Incident#167756)                                                                                  |
|                 | Resolved - C19 option for Lockout/Interlock Circuit not reflected on output submittal                                                                                    |
|                 | Resolved - Under specific scenarios when selecting Fire Pumps within approved range, error displayed for inaccurate selection [UK Market] (Incident #166059)             |
|                 | Resolved - After configuring replacement fire pump and driver, clicking Show Results displays error in grid results [Middle East Market]                                 |
| Heat Exchanger  | Resolved - In some scenarios the Fire pump submittal outlines inaccurate data points mapping                                                                             |
|                 | Resolved - When selecting Glycol, selection and output submittal incorrectly displays water (Incident #167034)                                                           |
| OEM             | Resolved - When selecting Glycol, selection and output submittal incorrectly displays water (Incident #167034)                                                           |
|                 | Resolved - unable to manual select Shell and Tube Heat Exchanger via OEM Heater method (Incident #168820)                                                                |
|                 | Resolved - Error displayed when selecting OEM Heaters (Incident #167241)                                                                                                 |
| Order Entry     | Resolved - Unable to select FTV during pump configurator selection [Brazil Market] (Incident #165707)                                                                    |
|                 | Resolved - Unexpected result displayed during order placement (Incident #167719)                                                                                         |
| Pumps           | Resolved - No-flow Shut-off inaccurately aligned on output curve (Incident #164959)                                                                                      |
|                 | Resolved - Inaccurate scaling on curve (Incident #165717)                                                                                                                |
|                 | Updated - Specific 4270 series pump model lead times (Incident #168128)                                                                                                  |
|                 | Updated - Lead Times for DEPM IVS (Incident #163540)                                                                                                                     |
| Selection       | Added - Brazil Market selection in ADEPT Select                                                                                                                          |
| Service         | Added - VMS Pump Parts Kits to Catalog selection [UK Market]                                                                                                             |
|                 | Updated - Submittal for specified Medium pumps inaccurate items removed                                                                                                  |
|                 | Resolved - Service and Parts 'Get Results' not displayed for 75hp pumps [NEMA Market]                                                                                    |
|                 | Updated - Required to enter serial number for each quantity requested, when selecting replacement drive or controller within DED or DEPC configurator (Incident #166659) |
| Tank Heaters    | Resolved - Incorrect submittal printed during selection of WX-1003                                                                                                       |
|                 | Added - Single click to switch between Imperial and SI units during SE ETS selection (Incident #165875)                                                                  |