



FILE NO.: 9.010
DATE: October 14, 2026
SUPERSEDES: 9.010
DATE: September 07, 2026

Product	Item Update Description
Boosters	Resolved - In certain scenarios, when opening older quotes, an error message is displayed
Expansion Tanks	Resolved - Incorrect accessories listed in Expansion System output quote documentation [UK Market] (Incident #212237)
Fire Systems	Updated - Lead Time for UK FM Jockey Pump Controller (Incident #215446)
	Resolved - When selecting Custom Request option, during Fire System Pump selection, it is not reflected in the Line Details in the cart (Incident #216452)
	Updated - During Vertical In-line Packaged Fire System (VIL FirePak) selection, if FlowMeter loop option and Citybypass loop option are selected, J Dimension is listed in the output submittal
	Added - Factory Acceptance Test (FAT), allowing our manufacturing plant to perform witness testing, is now available for Fire Systems [UK Market] (Incident #194256)
Pumps	Resolved - In certain scenarios, not able to email schedule document within ADEPT Select [India Market]
	Resolved - In specific 4300 pump selections, the pump curve is not displaying 2hp data point on curve (Incident #204636)
	Resolved - Lead time is inaccurately reflected when 4300 pump is selected with option for Pump Size 200-330, and Impeller Size 335 mm and above (Incident #211448)
	Updated - Lead time when selecting pumps up to 45 kW, 2/4 poles, IE3, with Factory Choice motor option and Casing Discharge up to 200 mm [India and Middle East Market] (Incident #211397)
	Resolved - When Choice Motor is selected with the Motor Supplier option set as CGL, Baldor, or WEG, lead time should be set as Consult Factory [India and Middle East Markets] (Incident #205934)
	Resolved - Specific Constant Speed 4360 pumps inaccurate lead time displayed (Incident #214632)
	Resolved - Sensorless Accuracy notification displayed incorrectly (Incident #214137)
	Updated - Lead time updated for specific IE4 motor selections (0.37kW-55kW ;> 200 kW) (Incident #216243)
	Incident #96883 VMS 2 pump selection in ADEPT not showing correct results - SQQ024965-5
Selection	Resolved - When requesting Non Catalog Price (NCP) within the Fire System selection, "Attention Required" appears after the NCP is approved (Incident #214171)
	Updated - Adjusted Rate Multiplier (ARM) approval workflow streamlined for initial request step (Incident #179766)
	Resolved - In some scenarios when selecting the "More" option for a line item in the quote, the displayed menu was located at top of quote
	Resolved - Approved Non Catalog Price (NCP) values are reverting to previous NCP approved values after initiating Consult Factory
Services	Updated - Not able to submit order without configuring Services when selecting replacement motor for in-field pump (Incident #211484)
	Updated - When selecting replacement pump parts, Services configuration is required, not allowing for order placement (Incident #213979)
	Updated - When System Envelope (SE) - F10/F20 Control Systems are selected with Design Envelope (DE) pumps, services are combined together [India Market]