

FILE NO.: 9.010 DATE: November 24, 2025

SUPERSEDES: 9.010 DATE: September 10, 2025

Product	Item Update Description
Boosters	Updated - Specific Booster model lead times
	Updated - DE (PM) 6800Q Lead time [India Market]
	Added - 7" HMI for Booster
Control Systems	Added - Enterprise Envelope (EE-W10 and EE-W20) available for selection [China, Asia Pacific Markets]
Fire Systems	Updated: Clarke Diesel base dimensions within selection and output report
	Incident #162390 RE: SA-6239896-Fire Pump set
	Updated - Fire Systems NPSHR point set to PSIa instead of PSI within configurator and output submittal
	Resolved - PLD Diesel Fire set selection, MVR and Waste Cone are not available selections within Accessories
	Resolved - Under certain selections sample data points and hp curve not accurate
	Added - 8x6x18PF CS VIL Fire Pump
	Added - 8x6x18PF DE VIL Fire Pump
Order Processing	Resolved - Inconsistent process during specific product ARM approval requests
Pumps	Resolved - DEVA not openning
	Resolved - Issue encountered during ARM approval request during specific Fire Pump selection
	Updated - Consult Factory allows for both days and weeks timeline
	Resolved - Pricing inaccuracte for OBS model
	Resolved - In some pump selection scenarios, the listed Grid price does not match the added to cart price
	Resolved - Specific pumps output submittal incorrectly outlines "No Sensorless Control"
	Resolved - Error in results provided during certain scenarios of Variable Speed pump selection
	Updated - Following pumps removed from manual selection option '0408-050.0' and '0513-040.0' [NEMA Market] / '1020-0.7.0' [IEC Market]
	Resolved - When selecting specific chiller replacements, inaccurate notice for risk of overloading is displayed.
	Resolved - Grid selection issues with 4300 - 2029B and 0811B DE models
	Added - Specific Medium pump models added to Pump configurator selection
	Removed - Sepcific pump models removed from pump configurator selection
	Resolved - Specific 4300 and 4380 pump curves inaccurate data displayed
	Added -TEFC Drip Cover
Services	Resolved - Post-pump configurator and select services included, error displayed [Brazil Market]
	Added - Medium Pump Motor addition to replacement configurator
	Added - DE Pump SMART Recommissioning