

Product	Item Update Description
Boosters	Resolved - Incorrect Booster Discharge Header Flange rating selection displayed on order (Incident #159238)
Expansion	Updated - Expansion product offering GLA 626/M and GLA626/L (Incident #156185)
Fire Systems	Updated - Gerrand flow meter model number updated (Incident #160379)
	Resolved - Error displayed when selecting Jockey pump within Service Parts and Kits during Accessories configuration [NEMA Market]
	Resolved - Power line data is missing in Submittal report during new selections
	Resolved - Specific Jockey Pump not able to add Service Kits [Asia Pacific Rim Market] (Incident #157575)
	Resolved - When configuring NFPA DE fire system, valid products are not displayed when clicking Get Results
LPC	Added - Features & Options for LPC selection (Incident #150745)
Order Submission	Disabled - Can not submit order when Expedite or Consult Factory is requested (Incident #153471)
	Updated - Change option to allow Place Order when Consult Factory or Expedite is requested.
	Resolved - Quote error when both NCP and Expedited/Consult Factory requested
Pumps	Updated - FTV Multiplier level setting fixed rate during Standard item selection [US Market] (Incident #161268)
	Updated - Lead time for FTS6V (Incident #160226)
	Updated - Accuracy of data in the Elastometric Flexible Coupling field within Submittal (Incident #161993)
	Updated - Update submittal for certain Compass R pump selections (Incident #161442)
	Resolved - error display when selecting single phase option during selection of 4280 DEPM [UK Market] (Incident #161047)
	Updated - Lead Time validation for various pump models. [Indian Market]
	Launch - DEPC card update 2.5 version release [Canada, Latin America, USA] (Incident #160654)
	Resolved - DE Pump model 4312-0208-015.0 missing full details when using Manual Select - Manual selection
	Added - Update various circulator models for DEPM inclusion (Incident #159259)
	Resolved - Error display when clicking on Curve during Constant Speed 4600 pump manual selection [India Market]
	Resolved - NPSHR incorrect value within Submittal document for specific 4700 series models (Incident #158802)
	Resolved - Error displayed when importing existing quote for Compass R20-35 SS and Compass H20-20 SS(0-10V) models [Latin America Market]
	Updated - Medium Pump VIL 3x3x7.5 Pump Curve Refit (Constant speed & Design Envelope)
	Updated - When selecting a pump, change ODP, 460/3/60 with export shipping, to TEFC 380/3/60 without export shipping [Brazil Market] (Incident #156371)
	Updated - Lead time for 4380 50-200 / 4380 32-120 (Incident #156340)
	Added - G30P seal [India Market] (Incident #155949)
	Added - DE 4300 Medium pump sizes 4x4x9.5 / 5x5x9.5 / 4300 6x6x9.5 / 8x8x11.5B
	Updated - Lead time inaccurate on select pump models
	Updated - Lead time inaccurate on select pump models
	Resolved - AHSRAE 90.1 compliance validated on specific pump models (Incident #137505)
Service	Updated - Accuracy of available pricing multipliers for various replacement motors (Incident #160106)
	Resolved - Pricing inaccurate between 7.5kw VFD with weather shield versus without weather shield (Incident #158424)
	Added - Serial number / SSID validation in Order Checklist page, during Place Order process
	Resolved - Error displayed when clicking Finish after selecting services during Services and Parts configuration process (Incident #151749)