



FILE NO.: 9.010
 DATE: April 07, 2026
 SUPERSEDES: 9.010
 DATE: February 11, 2026

Product	Item Update Description
Accessories	Resolved - Incorrect submittal produced when large size Suction Guides selected (Incident #183656)
Armstrong Integrated Designer	Resolved - Error displayed during printing submittal when selecting Armstrong Integrated Designer with Load Profile selections [UK Market] Resolved - When selecting System Envelope - Fluid Management Station (SE-FMS) within Armstrong Integrated Designer, and select Change Options, the displayed results are inaccurate [Canada Market]
Boosters	Resolved - Specific Booster models are displaying inaccurate selection warning message Resolved - When selecting specific Boosters, the Efficiency is inaccurately displayed
Fire Systems	Updated - The range of Design Envelope Fire pumps 5x4x9PF and 4x3x9PF (Incident#183592) Updated - DT2H-UFAA50, DT2H-UFAA58 engine models no longer available for selection (Incident #183249) Updated - Specific Fire System controller and option's Lead Time [Canada and USA Market] (Incident #181760) Updated - Witness Test option no longer available through selection options for Fire Pumps 14x10x20F & 12x8x20F
Heat Exchangers	Resolved - Incorrect dimensional drawing was selected for specific Shell and Tube Heat Exchangers (Incident #181457) Resolved - Under certain selections of Brazed Plate Heat Exchangers, requiring NCP request, the approved NSP request displayed an inaccurate Lead Time (Incident #181615)
Pumps	Resolved - Incorrect Lead Time displayed for specific Design Envelope 4382 pumps (Incident #183923) Resolved - Specific 4360 motor curve is not displayed in Single Curve chart (Incident#182887) Resolved - In certain cases, previous quotes were not updating Lead Time accurately for specific 4380 Design Envelope pumps [USA Market] (Incident #181802) Resolved - Under certain selections, when SSC-SSC G30P is included, pricing is inaccurately reflected [India Market] (Incident #182900) Updated - Heavy Duty Couplings renamed to Heavy Duty Couplings (Duraflex equivalent) and Standard Couplings renamed to Standard Couplings (Suraflex equivalent) for End Suction (4030) and Horizontal Split Case (4600) pumps [NEMA Market] (Incident #179944) Resolved - Lead Time for 4302 and 4382 pumps is missing "Weeks" notifier [Middle East Market] Resolved - Error displayed during selection when changing Fluid Option under Advance Options [IEC Markets] Added - 250hp option for the 10x10x14 4p pump (#1868376)
Selection	Resolved - Check Stock not functioning correctly [Brazil Market] Updated - User Defined Product selection now includes Custom Unlisted Fire Pump option [India Market] (Incident #184250) Added - Custom Fire Pump included in User Defined Products selection menu (Incident #177533)
Service	Added - 4332/4362 pump series to Replacement Drive Configurator selection option (Incident #176822)