

Descriptor	Item Update Summary
Accessories	Resolved - Flo-Trex Valve configurator displays incorrect pressure drop selection results
Boosters	Activated - DE 6900 model (Incident #136634)
	Updated - Pacdor images for CS VMS for boosters (DCR-2024-018)
	Updated - Selected Booster Pacdor data images (DCR-2024-005)
	Updated - For higher SCCR and individual disconnect for control panels, update to Double Stanchion Kit instead of single stanchion kit (Incident #133416)
	Resolved - "Critical error . ." displayed when selecting Submittal checkbox during Print output Booster 1560302 (Middle East, UK Markets)
Circulators	Added - Compass R40-85 and R60-50
	Updated - S&H Circulators Pacdor drawing details (DCR-2022-030) (Incident #81126)
Control Systems	Added - IPS Manager and SMART Start-up for DE IPS and IPS (DCR-2024-028)
Expansion	Updated - BMS Language Bacnet MS/TP selection part number not accurate.
Fire Systems	Updated - Fire pump fuel tank submittal report (Incident #81325)
	Updated - Fuel tank submittal based on fuel tank size
	Updated - Tornatech-GPD controller "Tropicalization" options set as "D12" instead of "D15" (Incident #87577)
	Updated - PLD - Clarke diesel engine pricing (Incident #132678)
	Updated - 4x3x9NF PacDOR (DCR)
	Updated - Item number for NFPA Loose Fire System Fuel Leak Sensor Switch (Incident#130313)
	Updated - Enclosed Fire Package pricing (US, Canada, Latin America Markets) (Incident #136800)
	Added - Fire DE pump 4x3x10 PF
Heat Exchanger	Resolved - FW: Plate and Frame Heat Exchanger order entry (Incident #135225)
iFMS	Updated - iFMSSG not available to select Suction Guide option (Incident #80364)
	Resolved - IPS/IPC Controller checkbox unselectable for 4-5 pump quantity (Incident #132383)
LPC	Added - LPC Fire System Hazzard Class to output Quote and Submittal (Incident #128783)
Quoting	Added - Checkbox to indicate the quote reflects requirement of an Energy Upgrade project.
Parts/Service	Updated - Specification text in G30/G30P and D4 seals report
	Updated - DEPM2 & iECM parts selection - enable limit of power supply, HP, RPM based on motor part number
	Added - DEPM (DE 4200H, DE 4280) and DEPM IVS (DE 4200H) end suction, Touchscreen cover is now standard inclusion (Incident #130416)
	Removed - Medium pump 6" ES Spring Isolator service kits removed from selection (Incident #133504)

Descriptor	Item Update Summary
Pumps	Activated - Medium Pump ES 6inch-Manual selection (DCR-2024-011)
	Changed - IE4 set as default within selection (China Market) (Incident #135693)
	Updated - Features and options for DE 4200H and 4280 selection of custom motor (Incident #70638)
	Resolved - Motor Supplier selection for WEG displaying error (Incident #60452)
	Resolved - DE Controls Replacement parts specification report displayed blank when open
	Resolved - Cannot select threaded valve after selecting required 2" or smaller FTV (Incident #85356)
	Updated - DE 4300-5048-500.0 - 500kw set as standalone pump (UK Market) (Incident #130934)
	Added - 575/3/60 power supply option now available for DEPM pumps (USA Market) (Incident #133929)
	Added - Display notice for pre-launch products.
	Added - Lead time notification for pre-launch products
	Resolved - Lead Time inaccurate for Customer Choice Motor selection (India Market) (Incident #134261)
	Resolved - Blank pop up message is displaying for Conventional - Variable Speed pump models (4300,4380,4360,4030,4280,4600) (NEMA Market)
	Resolved - error displayed when selecting Flo-Trex Valve FTV-6FA (UK Market) (Incident #129771)
	Updated - Lead Time for specific pump/motor selections (USA, Latin America Market) (Incident #134614)
	Validated - Lead Time discrepancy for specific pump/motor selections (#135543)
	Updated - IE4 Efficiency motor Lead Time (India, MEA Market) (Incident #135697)
	Updated - Weight listing for the DEPM (Small Gen 5) pump family (Incident #135735)
	Added - Angle/V-cut indicator in selection options (Incident #135747)
	Added - NPSHr value included in features and options details (Incident #135744)
	Service
Resolved - Error 500 when selecting CustPump option Incident (#136206)	
Resolved - Error message when selecting/editing 208/3/60 variable pumps (Incident #136231)	
Sustainability	Validated - DE4300-2533-022.0 reported not available for auto select (Incident #108980) Updated - SMART Recommission configurator verbiage. Pump serial number set mandatory input (Incident #131232) Resolved - "Please refresh browser" message displayed during quote creation under specific login conditions (Incident #133097) Updated - Fire system Pump Commissioning pricing (UK Market) (Incident #136597) Updated - Changes / Additions to TM65 report data