

Product	Item Update Description
Armstrong Integrated Designer	Resolved - When selecting through Armstrong Integrated Designer, error occurred when trying to print Submittal [Brazil Market]
Boosters	Remove - 6900 Booster family (Incident #178787)
	Remove - Various Design Envelope Booster 6800/G/Q models
	Resolved - Specific Booster models not displayed accurately in Search Results (Incident #165671)
Control Systems	Updated - IPS Connectivity Kit item number and price listing [India Market] (Incident #178982)
DEVA	Resolved - DEVA report not output printing under certain model specifications
	Resolved - DEVA not available for selection [Brazil Market] (Incident #165374)
Fire Systems	Resolved - In certain selection scenarios, the unit of weight was display in KG instead of LB
	Update - Lead Time adjustments for Fire Systems [US and Canada Markets] (Incident #179705)
Heat Exchanger	Resolved - Unable to request ARM approval for specific Design Envelop Heat Exchangers (Incident #179446)
	Updated - Various data points within the output Submittal for Shell and Tube
Parts	Updated - When selecting certain replacement drive products, the Pump Size is not accurately listed in the Submittal report
Pump Accessories	Resolved - In certain pump accessory selections, Submittal output was not generated (Incident #181218)
Pumps	Resolved - Error 500 displayed during conversion and update location listing [Americas Market] (Incident #181142)
	Resolved - Error 500 displayed when selecting System Type for SE-FMS
	Updated - Lead time for Constant Speed - 4300 - 200- 375 - 4p - 45 kW adjusted to 5 weeks [India Market]
	Updated - VFD Submittal addition of Meets ASHRAE field
	Updated - PEI and ER data for various Medium pump models (Incident#178503/178494)
	Resolved - Pump 4300 DE IVS Sensorless curve display error (Incident#178683)
	Resolved - Pump model 4200H 6519-30kW - Inlet size inaccurate (Incident#178386)
	Resolved - Inaccurate curve data and selection pump model 4270 1.5x1.25x5.5 (Incidents#174562)
	Resolved - Calculate button not visible under all selection instances
	Resolved - Error 500 displayed when selecting 710kw motor [India Market]
Selection	Resolved - Under specific duty points, during pump model 4332 - 1015B-011.0 selection, Sensorless area inaccurately displayed [India Market]
	Updated - Output report inconsistent header formatting
Services	Updated - SMART Startup & SMART Startup+ pricing update (Incident #177625)