

External List	
Product	Item Update Description
Circulators	Launch - S&H Maintenance Free (MF) Circulators
Expansion Tanks	Resolved - Specific GLA Standard and GLA Ultra models lead times not accurate during selection (Incident #205504)
Fire Systems	Updated - Included BS-Energize To Stop Timer Relay option during Eaton Diesel Controller selection, to output report documentation
	Resolved - In some selection scenarios, UL Approval and FM Approval options inaccurate based on selection specifications (Incident #201911)
	Launch - Available 3 Year warranty included when selecting 3 years of Fire Pump Manager (Core) (Incident #201651)
	Updated - Curve for various 8x6x10NF, NA8x6x10N, 5x4x10F, and NA5x4x10L models.
	Resolved - Various Diesel Fire Pumps not listed within the search grid results (Incident #196948)
	Updated - Withstand Rating for Electric Tornatech Fire controller [Except GPL and GPL-GLU type controller] (Incident #197940)
	Resolved - In some selection scenarios, the incorrect engine may have been selecting for the diesel Fire Systems (Incident #195922)
Pumps	Updated - NFPA Design Envelope pumps displayed in Search results [Brazil Market]
	Validated - Specific lead times accurate for pumps which include Non-Standard Motor option (Incident #203426)
	Updated - Specific Pumps and pump accessories lead time has been updated
	Resolved - In certain selection scenarios, when Pump Kit option is selected, the Lead Time displayed was not accurate. (Incident #202409)
	Resolved - Circulator manual selection for certain models does not allow for Automatic grid option (Incident #201450)
	Updated - Product Lead Time update for certain pump models [Outside the Americas Market] (Incident #202361)
	Resolved - Certain 4280 pump models inaccurate frame option selection pricing (Incident #188639)
	Resolved - Lead Time inaccurate on specific pump model (Incident #198695)
	Removed - Pump model 4280 150-400-55kW removed from selection [UK Market] (Incident 196042)
	Resolved - In some selection scenarios when a Suction Guide is included during Configuration selection of the pump, the Lead Time displayed was not accurate. (Incident #187313)
	Resolved - in certain 4030 pump model selection scenarios, the incorrect motor is included (Incident #78092)
Services	Updated - Design Envelope pumps over 7.5hp/kW now include Smart Start-up service as default option
Service Parts	Added - FactorySet Parameter option within the Replacement Drive Configurator for the iECM/DEPM2 drive type (Incident #199064)
	Resolved - In some selection scenarios, incorrect motor option is included during Medium Pump Replacement Configurator (Incident #200140)