



FILE NO.: 9.010  
 DATE: June 22, 2026  
 SUPERSEDES: 9.010  
 DATE: May 15, 2026

Product	Item Update Description
Air Separators	Updated - Lead time for specific Vortex Air Separators (Incident #198208)
Boosters	Updated - Minimum pressure range option selection start at 0 psi [Latin America Market] (Incident #196328)
Circulators	Resolved - Specific small Circulator pumps not available during selection (Incident#190458)
Expansion Tanks	Added - New GLA models available [Continental Europe, Middle East, UK Markets] (Incident #194012)
Fire Systems	Resolved - In specific pump selections, inaccurate Main Relief Valve (MRV) is included in selection options (Incident #199273)
	Resolved - Error displayed during selection of 8x6x13FM pump model (Incident #199778)
	Updated - Specific Fire pump models displayed inaccurate pricing after selection completed
	Removed - Cummins Engine option from selection (Incident #195541)
Heat Exchangers	Resolved - Selecting Stainless Steel shell is not reflected when product is added to the cart (Incident #197161)
	Resolved - Specification report shows inaccurate material data
Pumps	Resolved - Under specific pump model Change Options from cart selection, an error may be displayed preventing changes to be entered (Incident #198091)
	Updated - Specific E-Series model weight listings (Incident #188483)
	Added - Activated various pump models within selection options (Incident #192549)
	Resolved - On specific 4380 2x2x6 pump models, inaccurate motor hp curve displayed (Incident# 146768)
	Updated - Specific VIL and ES product curves (Incident#193136)
	Resolved - Specific 5hp pump models are not available to be selected
	Updated - Pump model 4700 VMS 0502B not able to be selected consistently. (Incident #200776)
	Updated - Motor selection alignment with pump models (Incident#201231)
	Resolved - Specific pump model selections result with inaccurate non-compliant notices (Incident#200353)
	Resolved - Specific 4200H model pumps hp selection inaccurate (Incident #99651)
	Resolved - Certain 4300 pump models with 1800 rpm requirements available for auto select in 60 hz [Middle East Market] (Incident#201345)
Service Parts	Launch - System Envelope - Energy Transfer Station (SE-ETS) Parts Kits
	Resolved - In various replacement motor selection scenarios, an inaccurate price was listed. specific motor selection resulted in (Incident# 198684 Urgent)