

Product	Item Update Summary
Boosters	Resolved - DE Booster selecting BACnet during selection reverts to Modbus after selection added [UK and Middle East Markets] (Incident #139291)
Circulators	Updated - "Potable/Drinking Water" set as default for domestic application Compass R40-85 SS and Compass R60-50 SS. (Incident #140085)
Expansion	Updated - Model list for 3760 PU unit in manual selection [UK and Middle East Markets] (Incident #136977)
	<p>Added - New VIL Fire Pump 4X3X9NF (DCR-2025-001)</p> <p>Added - New - High Flow High Head Fire Pump - 12x8x20F (DCR-2022-025)</p> <p>Resolved - When selecting D26-ModbusRTU, does not list on Quote document output [Middle East Market] (Incident #132491)</p> <p>Resolved - inconsistency of Manufacturer and Driver option matching selected Fire Controller, Driver and Fire pump (Incident #135796)</p> <p>Removed - HSC/ES and VT Fire pump Cummins Engine CFP9E-F65, CFP9E-F75, CFP9E-F85, CFP15E-F10, CFP15E-F20, and CFP15E-F30, CFP15E-F70 [Except UK and Europe Markets] (Incident #136824)</p> <p>Updated - Description verbiage for Minimum Fittings for Electrical End suction fire pump and VIL FIRE pump (Incident #136823)</p> <p>Resolved - Error displayed when selecting Download prior to adding selection to quote for DE 43PF 4310B-AA-030-O [CA Market]</p> <p>Updated - 6x5x12F & 8x6x15NF peak power table and curve data (Incident #138834 / 138978)</p> <p>Resolved - When selecting Electrical fire pump with the "Enclosure package", LSCV can be selected as an option (Incident #139756)</p> <p>Resolved - Fuel Tank Selection Option not displaying accurate tank size, based on selected options and engine model. [UK Market] (Incident #139775)</p>
Heat Exchangers	Resolved - Shell & Tube Heat Exchange unit value mismatch between selection and submittal output
Order Submission	Resolved - Inconsistent spare parts orders displaying error when selecting Place Order [Middle East Market]
Pumps	<p>Changed - Pump 7.5hp/kw and above, default inclusion of Smart Start-Up</p> <p>Enabled - Various Medium Pump DE Models in Manual Select (DCR-2024-030)</p> <p>Changed - Clarified displayed message to go to Service and Parts, with Pump Manager and Smart Start-up included</p> <p>Resolved - In some scenarios when Residential Pumps are selected and a NCP is requested, the NCP status remained as Pending</p> <p>Resolved - The Outer Casing O-Ring is not listed in the Quote print out item details (Incident #131368)</p> <p>Removed - 4380 3213H Pump Manual Selection [Except United Kingdom Market] (Incident #131222)</p> <p>Resolved - Line item comments not transferring to "External comment" field on submittal document output (Incident #132588)</p> <p>Removed - Motor model 15hp/208V/215FR/TEFC [NEMA Market] (Incident #125901)</p> <p>Validated - 4200H DEPM IVS Sensorless pump series outlines Consult Factory</p> <p>Validated - ADEPT Select error displayed when selecting Download Schedule or Download line item</p> <p>Resolved - Error 500 displayed when selecting "Flo-Trex Valve" and "Suction Guides" through CS4380 pumps configurator [India and China Markets]</p>

Product	Item Update Summary
Pumps	Updated - Lead time for pump motor selection 3 hp, OTD, 184TC, 1800 RPM, Standard Eff., 230/1/60 [CA, US, Latin America Markets] (Incident #138896)
	Resolved - Inaccurate impeller size for specific pumps resulting in inconsistent curve selection data (Incident #137477)
	Resolved - Selecting IE4 Efficient Motor results in error [Asia Pacific Market] (Incident #139231)
	Enabled - IE3 motor option for the models 4300-350-350-4p-160kW & 4300-350-350-4p-200 kW. [Middle East Market] (Incident #137475 IE3)
	Resolved - under certain scenarios, importing quote resulted in pricing missing (Incident #138982)
	Resolved - Parallel Sensorless pricing missing after validating quote (Incident #138566)
	Resolved - Selecting specific pump with PreLaunch status, resulted in error message displayed [IEC Market]
	Resolved - When configuring Tango 4332, option for Suction Guide is not available (Incident #140817)
	Updated - Medium Pump Models Displayed in Manual Selection Dropdown
	Update - IPS System quote submit to order process, IPS Manager optional
	Resolved - Error message displayed when selecting submit order after adding Service and Parts to Automation and Controls items
	Resolved - In specific cases, unable to configure 4362 Pump with specific requirements
	Selection Process
Service	Added - Filter Cartridge option under Add Service Kits option during pump selection (Incident #137426)