

Product	Item Update Description
Armstrong Integrated Designer	Resolved - Error 500 displayed when selecting Load Profile feature, under certain selection parameters
Control Systems	Updated - When IPS4000 or IPS4500 is selected, the Enclosure Rating field is now available for IP54 and IP55 option selection. [India and Sout Asia Market] (Incident #187669)
Expansion	Resolved - Enterprise Envelope W20 output submittal inconsistency in option's text (Incident #185927)
	Updated - Expansion Tank various item numbers and pricing alignment (Incident #177413)
Fire Systems	Resolved - In certain selections, Design Envelope Fire Pump 75hp (208/3/60) output part number is misaligned
	Resolved - In certain NFPA Fire Systems pump selection, the output submittal did not reflect selection for the Pump Start Push Button option (Incident #187621)
	Updated - Lead Time for Fire pump 12x8x18NF (Incident #186966)
	Updated - FM Fire pump Lead Time [UK Market] (Incident #186940)
	Removed - Engine models - DT2H-UFAA50, DT2H-UFAA58 - removed for selection option (Incident #183249)
	Updated - Result grid for 208/3//60 Fire System pumps up to 60 hp
	Resolved - Full results not displayed when Type of Duty option was set to Fully Calculated
	Resolved - When selecting Fully Calculated in System duty, with USgpm and kPA units, error in curve was displayed
Resolved - Error during selection of Wet Riser option (Incident #176663)	
Heat Exchangers	Resolved - Inconsistent selection output for various Shell and Tube Heat Exchangers (over 14" size) when changing from Carbon Steel to Stainless Steel shell material (Incident #187583)
OEM	Updated - Certain pump selections now includes Customer-Supplied-Motor option (Incident #178442)
Parts	Added - DEPM2 / IECM under the Drive Type dropdown menu list for Booster in Replacement Drive configurator
	Resolved - In certain scenarios, inaccurately part number was displayed when selecting Replacement DEPC [IEC Market]
Pumps	Resolved - Can not add 4380 4x4x13 pump to schedule under specific specifications (Incident #184824)
	Resolved - In certain cases, ARM approved produced quote inconsistency (Incident #185265)
	Resolved - Inconsistent curve displays on specific pump models (Incident #184573)
	Updated - S & H Series Circulators (5 and 6 Series) Lead Time (Incident #183220)
	Updated - Certain 4300 pump models inconsistent grid results.
	Resolved - Constant Speed pump 4380 200-315-45 kW error displayed on pump selection from grid results [UK Market]
	Resolved - Under specific duty points, displayed curve is in accurate (Incident #138955)
	Resolved - With specific duty point selection for Constant Speed pump with 1hp motor, the Add function is not available (Incident #129365)
	Resolved - 4030 3x2.25x10 inaccurate curve displayed (Incident #110419)
	Resolved - Specific duty point for 4300 6x6x11.5 pump results inaccurate curve displayed (Incident #96919)
Resolved - Inconsistent displayed curve on specific pump models (Incident #100749)	
Service	Resolved - In certain cases, when selecting a Connectivity Kit with Pump Manager Service, an error is displayed with selection window restarting (Incident #165544)