

Product	Item Update Description
Boosters	Resolved - During specific Booster selections, Discharge Flange rating displayed was inaccurate (Incident #195639)
	Resolved - Selecting a quote with approved NCP request, results in error displayed
Fire Systems	Resolved - Incorrect Pump Type option is displayed during specific 7280 or 7030 pump selection parameters (Incident #193367)
	Resolved - Specific LPC selections displayed inaccurate single pump curve duty points (Incident 183528)
	Resolved - Under certain selection parameters, after NCP is approved, error message may be displayed (Incident #193672)
	Resolved - Under specific duty conditions during Fire Pump selection, the Tornatech controller option, displays incorrect rating hp (Incident #192663)
	Resolved - Inaccurate grid results during specific Fire Pump selection (Incident #196938)
	Resolved - Under certain selection parameters, the submittal report unit of measurement is not accurate, except in BAR units [Asia Pacific Rim Market]
	Resolved - When selecting BS9990- WET RISERS-eMPA pump selection peak power, inaccurate output selection of motor (Incident 195706)
	Resolved - In certain selections of LPC 8x6x13, Pre-Calculated option under Type of Duty, inaccurate grid results displayed (Incident #192926)
	Resolved - In some selection scenarios, when custom option is selected and NCP is approved, Lead Time does not change "Consult Factory" to number of expected weeks (Incident #194633)
Pump Accessories	Resolved - In certain Suction Guide or Flo-Trex Valve selections, the item number was inaccurate [UK Market] (Incident #194857)
	Resolved - In some scenarios after NCP request approved, Lead time displays inaccurate number of weeks (Incident #192118)
	Resolved - Add to Scheduled is greyed out for specific 4300 DEPM IVS pump models (Incident #194183)
	Resolved - During specific pump selection, "Full Capability Head" at design flow was not accurately displayed (Incident #195826)
	Resolved - Inaccurate horsepower displayed with specific pump model selection (Incident #104491)
	Resolved - Inaccurate Lead Time displayed for specific 4300 pump models (Incident #194856)
	Resolved - On specific 4200H pumps, the Outlet displayed was inaccurate (Incident 197809)
	Resolved - Specific 4300 pump model with 45kw motor, curve displayed is inaccurate (Incident #137679)
	Resolved - Specific pump model Lead Time not accurate
	Updated - Spare Parts listing move to the end of the quote report, for simpler access to listing (Incident #127574)
	Updated - Specific Design Envelope 4200H pump models only available through manual selection option
	Updated - Specific Design Envelope IVS 4300 pumps Lead Time (Incident #189212)
	Added - Bolting Down costs and outline now included in output Quote and Scope of Supply [UK Market]
	Service Parts
Resolved - During specific Replacement Drive selections, unable to print of Submittal pricing document (Incident #196669)	
Updated - Include initial question guide during Motor Replacement Configurator selection (Incident #195321)	
Services	Resolved - Under specific selection, error 500 displayed during Services and Parts usage
	Updated - Under certain scenarios within Services and Parts configurator, changing quantity for number of rooms, results in error being displayed.
Sustainability	Added - Pump model based Carbon Statement added to Submittal report