

External List	
Product	Item Update Description
Armstrong Integrated Designer	Resolved - When making selection through the Armstrong Integrated Designer, Efficiency Curve displays inaccurate Maximum Efficiency point [Canada and USA Markets] (Incident #164551)
Fire Systems	Update - Diesel engine Typical specification report (Incident #199616)
	Resolved - Inaccurate pump model listed within results grid for specific duty condition (Incident #207352)
	Resolved - Selection results included inaccurate pump model in results grid (Incident #209108)
Heat Exchangers	Resolved - Inaccurate temperature rating listed when brass tube sheet material option is selected (Incident #184486)
	Enabled - Braze Plate Heat Exchanger Configurator now available in ADEPT Select for specific regions (Incident #206519)
Pumps	Resolved - During selection of certain pump models, the listed weight for the pump is inaccurate (Incident #202532)
	Updated - Lead times have been updated for various products [Asia Pacific Markets, China, India and Middle East Markets]
	Updated - Specific DE Medium pump model line drawings [DCR-2026-001]
	Resolved - When printing Design Envelope Pump specification within ADEPT Select, the output is showing inconsistent formatting
Service Parts	Changed - Controls Replacement Parts configurator has been changed to Optimization and Controls Parts Kits
	Resolved - Various 4300 pump family models Recommended Spare Parts and Kits option, not listed within selection (Incident #191197)
Services	Update - When selecting Design Envelope pumps over 7.5hp/kW, Services configuration required prior to submitting order