

DATE: June 19, 2024

Descriptor	Item Update Summary
Accessories	Validate Suction Guide pressure drop data (Incident #113761)
	Resolved - Suction Guide Selection - Connection Size
	Expansion Tank-ASME (Incident #110771)
	Resolved - Expansion System vessel selection options - (K1903/544 - Reflex DE 1000) (Incident #113617)
	Addition - Locally sourced Boosters (DCR-2024-005)
ADEPT Select	Resolved - Error displayed when importing quote from ADEPT Select
Circulators	Resolved - Download not possible for BIMs, Models & Drawings in post select page for AGE4 (UK/ME)
	Added - AGE4 Union kit notification
Fire Systems	Fire 4136 Rated Flow should be 3500USGPM for Main Relief Valve and Waste Cone as per System duty and locked (Incident #117407)
	Resolved - Fire Controller set up issue (Incident #117081)
	Eaton controller FD30 Allowing Single Phase Selection (Incident #117377)
	DE Fire - FirePak List Price (Incident #118091)
	Validation - Lead Time Fire pump model 14x10x20F, Horizontal Split Case & ES Diesel driven with Kirloskar Engine, standard motor, and Clarke Engine and Fire pump and Motor
	Update - Bushing size on LPC Electric Fire pump (Incident #118728)
Guidance	Update to Special Shipping Instructions for 'Call before Manufacture' feature
Lead Times	Update - Pump Shipments with Low Margin May 2024 (Incident #119911)
Order Submission	Resolved - View Order Summary unspecified error
	Quote pricing validation (Incident #114485)
	Validate - ADEPT Multiplier (Incident #118419)
	Address 1 filed is enabled when change to "Same as Bill-to" option (UK Direct Market)
Pumps	Resolved - Error when selecting Calculate during pumps manual select
	Resolved - Pumps manual select not working for 4300 0205-002.0 where head is passed as zero
	Validate ADEPT quote for TRANE (Incident #116095)
	Resolved - Error 500 on OEM-DAIKIN -NEMA
	Resolved - Medium pump DE 4332- Shipment Indicator is missing in post select.
	Resolved - LA Configurations missing Pump option set (Incident #119027)



FILE NO.: 9.010 DATE: July 02, 2024 SUPERSEDES: 9.010

DATE: June 19, 2024

Descriptor	Item Update Summary
Pumps	Resolved - Error 500 on pump series 4700 and 4360 (OEM - All NEMA Market)
	Transpose axes of Load Profile UI
	3760 Pro 2HP unit submittal data (Incident #107173)
	Update Configuration for new Pumping System selection
	Update - 4300 and 4380 3x3x6B CDN Price List (Incident #112206)
	Addition - Service Kits Menu for 4360-3D-4p-1.5hp model (Incident #115490)
	Medium Pump Tango Report template creation (DCR-2024-009)
	Modification - Buy American Lead Time modified to 20 weeks (Incident #117094)
	Remove - 0.55kW from grid results for 32-105 and 25-90 UK VS selections
	Removal - Mechanical Seal kit from pump accessories for long coupled Pumps (Split Coupled) (Incident #118331)
	Update - Data Migration for 4x3x9PF VIL pacdor package
	Re-instate DE pump selections
Selection	Validated - ADEPT and documents in ADEPT different (Incident #117704)
	Resolved - Inaccurate wording in Adept (Incident #118101)
	Validate - New User Task; Review and update NCP Price - SQJMJ000790_2_6
	Update - Changes to Load Profile demo
	Update - TM65 report data
	SO# 82S000768 , Project Name : SRM Hostel_Kattankulathur - DTA (Incident #118080)
	Addition - turndown ratio